RCC. A. pointer meet jad 12/13 UTAH COPPER DIVISION folin LCGingha
MINING AND RECLAMATION PLAN

Mining And Reclamation Plan

Mining A

1. Mine Area

During Operations

1. Maintain stable side slopes generally averaging between 25° to 29° fr

After Conclusion or When No Longer, Needed

- Leave side slopes in stable condition between 32° to 37° from horizont
- Provide means of safe disposition for pit drainage water.
- 3. Raze or remove surface facilities. .

2. Mine Waste Disposal Area

During Operations

- 1. Monitor dumps for stability.
- Test vegetation possibilities.
- Maintain dikes and ponds.

After Conclusion or When No Longer Needed.

- Stabilize dumps by terracing and hydraulic methods.
- Raze or remove surface facilities

3. Excess Mine Water Disposal Area

During Operations

1. Maintain dikes for safe containment of excess mine water.

2,000/m. 2. Test vegetation methods.

After Conclusion or When No Longer Needed

Remove or cover accumulated salts, treat with neutralizers, grade and vegetate as required.

Ore Transfer - Mine to Process Area

During Operations

2. Stabelize

No specific work contemplated.

After Conclusion or When No Longer Needed

1. Remove surface facilities.

2 or, our to take at fronk

word of South fordown Transferrate who

0002

all Salvage expenditures are

5. Ore Processing Facilities Area

During Operations

No specific work contemplated.

After Conclusion or When No Longer Needel

- 1. Raze or remove surface facilities 500,000
- 2. Eliminate hazardous conditions. /00,000
- 3. Stabilize and revegetate as required. 100,000
- 6. Tailing Disposal Area 6000 AC.
 Raises 3/year in elevation.

During Operations

- 1. Stabilize dike by maintaining 5 to 1 slage and conducting periodic inspections by consultants.
- 2. Stabilize dike top surface and roads with stabilizing agent such as Coherex. (\$1,000) operational

3. Stabilize dike outer surface with vegetation.

4. Stabilize surface of pond by wetting from peripherical line, application of agents by land vehicles or airplane (\$40,000 operations)

5. Test vegetation methods on surface of good.

After Conclusion or When No Longer Needed

- 1. Complete necessary dike stabilization. undeterminate
- 2. Vegetate pond surface if determined practicable. 200,000

7. Excess Process Water Disposal Area

During Operations

- 1. Maintain dikes for safe containment of excess process water.
- 2. Sofety considerations
 After Conclusion or When No Longer Needed
- 1. Raze or remove surface facilities.
- 2. Leave sludge ponds, evaporation ponds and other disturbed areas in condition suitable for other use determined at conclusion. 5 00,000

*

1000